PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service
No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date : .....*

YIELD REPORT

1. Name and Address of the Party : AEE, ward 12 shettyLalli BBMP
2. Borewell Location : shettyLalli 6th cross shettyLalli village.
3. Total Depth Drilled : 934.8 fts
4. Casing Pipe : 275 fts
5. Coupling : 23 nos
6. Yield Details :
   a) First Spring Touched at : 300 fts
   b) Second Spring Touched at : 540 fts
   c) Third Spring Touched at : 880 fts
7. Total Yield in G.P.H. : 1650 G.P.H
8. Remarks : yields good

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M B Mohan Reddy

Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* .....

YIELD REPORT

1. Name and Address of the Party : AEE ward 12 shettyhalli BBMP
2. Borewell Location : shettyhalli next to Door no. 39
3. Total Depth Drilled : 902 fts.
4. Casing Pipe : 262 fts
5. Coupling : 23 nos
6. Yield Details :
   a) First Spring Touched at : 280 fts.
   b) Second Spring Touched at : 570 fts.
   c) Third Spring Touched at : 820 fts.
7. Total Yield in G.P.H. : 1500 G.P.H.
8. Remarks : Yields good.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

For PALLAVI BOREWELL & DRILLERS

M B Nirvan Reddy

Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date :* .....

YIELD REPORT

1. Name and Address of the Party : AEE ward 12 Shettyhalli BB MP
2. Borewell Location : R.R. Layout main Road Door no - 100
3. Total Depth Drilled : 918 ft.
4. Casing Pipe : 269 ft.
5. Coupling : 25 nos.
6. Yield Details :
   a) First Spring Touched at : 340 fts
   b) Second Spring Touched at : 600 fts
   c) Third Spring Touched at : 860 fts.
7. Total Yield in G.P.H. : 1700 fts
8. Remarks : yields good.

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ರಾಜರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

For PALLAVI BOREWELL & DRILLERS

M B Nirmal Kumar

Proprietor

PALLAVI BOREWELL & DRILLERS

Dealers in : 6½" 4½" Borewells Drilling & Inwell Drilling
All Kinds of Motors & Pumps, Sales & Service

No. 66/8, 1st Main Road, Maruthi Layout, M. G. Road,
Nelamangala Bangalore - 562 123.
Moble : 93412 24311, 90089 87530,



Ref : *Date : .....*

YIELD REPORT

1. Name and Address of the Party : AEE ward 12 DSHethyalli BBMP
2. Borewell Location : Raghavendra layout 2nd cross
3. Total Depth Drilled : 879 fts
4. Casing Pipe : 262 fts
5. Coupling : 23 nos
6. Yield Details :
   a) First Spring Touched at : 260 fts.
   b) Second Spring Touched at : 480 fts.
   c) Third Spring Touched at : 720 fts.
7. Total Yield in G.P.H. : 1400 G.P.H.
8. Remarks : Yields good.

For **PALLAVI BOREWELL & DRILLERS**

M B Manjunath
Proprietor

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಬ್ಬಹಳ್ಳಿ ಉಪವಿಭಾಗ, ಹೊಸರಹಳ್ಳಿ ಪಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. :

To the Asst Executive Engineer Date :
BBMP

1. Name of the Customer
2. Location. Ward No:- 12 Dasarahalli Zone
   a) Village Rajaveedhi equil- 2nd cross b) Block / Taluk. Seltyhalli c) District Bangalore
3. Lithology of the Area Granetic / Gneissic in nature
4. Tophographic Features of the Area The area was a plain land
5. Hydrogeological condition of the Area Good
6. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 300'?
      520 - 570'
      960 - 990'
      } 2
   e) Condition of Ground Water. Good -
7. Type of well Recommended. Bore well ($6\frac{1}{2}$")
8. Depth Recommended. 900 - 940'
9. Expected Yield. 1500 - 1600 GPH
10. Quality of Water. Good -
11. Approximate depth at which the water is expected to be met. Around 300'?
12. Recommended Type and Length of casing to be inserted. nearly 250 - 280' of MS Casing way & needed
13. Rain water Harvesting adviced or not - Strictly adviced -
14. Remarks.

AEE
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. : To the Asst Executive Engineer Date :
BBMP
Dasarahalli Zone
Settyhalli

1. Name of the Customer
2. a) Village Ward No: - 12 Shettyhalli Door No: 35 b) Block / Taluk. Settyhalli c) District Bangalore
3. Location.
4. Lithology of the Area Granetic Gneiss in nature -
5. Tophographic Features of the Area The area was a plain land
6. Hydrogeological condition of the Area Good -
7. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 30c' ?
      580 - 630'
      830 - 870' } 2
   e) Condition of Ground Water. Good -
8. Type of well Recommended. Bore well (6 1/2")
9. Depth Recommended. 950 - 980'
10. Quality of Water. 1600 - 1800 GPD
11. Approximate depth at which the water is expected to be met. Good
12. Recommended Type and Length of casing to be inserted. Around 300' ?
13. Rain water Harvesting adviced or not Nearby 260 - 280' of MS Casing may be needed
14. Remarks. Strictly Adviced -

AE 12
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಟಿಸ್.ಬಿ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು.

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. : To the Asst Executive Engineer Date :
BBMP
Dasarahalli zone

1. Name of the Customer
2. a) Village Ward No:- 12 Sethy halli b) Block / Taluk. c) District
3. Location.
4. Lithology of the Area Granetic / Schistose in nature
5. Tophographic Features of the Area The aere was a plain land
6. Hydrogeological condition of the Area Good
7. Geophysical survey result. By Diving methods
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 350' ?
      550 - 580'
      890 - 940'
      } 2
   e) Condition of Ground Water. Good
8. Type of well Recommended. Bore well (6 1/2")
9. Depth Recommended. 950 - 980'
10. Quality of Water. 1700 - 1800 GPH
11. Approximate depth at which the water is expected to be met. Around 350' ?
12. Recommended Type and Length of casing to be inserted. nearly 280 - 290' of MS Casing may be needed
13. Rain water Harvesting adviced or not Strictly Advices
14. Remarks.

AEIL
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.

A. N. CHOWDHARY, M.Sc.,
GEOLOGIST
Cell : 98454 73398

SRI SHIRDI SAI CONSULTANTS

10, 3rd Floor, 19th Cross, 14th Main, Revenue Layout, Padamanabhanagar,
Bangalore - 560 061.

GROUND WATER INVESTIGATION REPORT

S. No. : To the Assistant Executive Engineer BBMP Dasarahalli Zone, Bangalore Date :

1. Name of the Customer
2. a) Village Ward No:-12 Setty halli b) Block / Taluk. c) District Bangalore
3. Location. R R layout main Road Door No:100
4. Lithology of the Area Granetic Schistose in nature
5. Tophographic Features of the Area The area was a plain ours
6. Hydrogeological condition of the Area Good
7. Geophysical survey result. By Diving method
   a) Type of Method.
   b) No of Soundings Conducted.
   c) Recommended Sounding.
   d) Particulars of formations present in the subsurface/possible ground water zones encountered at
      Around 35c'?
      600 - 67c'
      850 - 88c'
      2
   e) Condition of Ground Water. Good
8. Type of well Recommended. Borewell ($6\frac{1}{2}$")
9. Depth Recommended. 930 - 960'
10. Expected Yield. 1800 - 2000 GPH
11. Quality of Water. Good
12. Approximate depth at which the water is expected to be met. Around 35c'?
13. Recommended Type and Length of casing to be inserted. nearly 250 - 280' of MS Casing may be needed
14. Rain water Harvesting adviced or not — Strictly Adviced
15. Remarks.

AE IL
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ಮಲ್ಲೇಶ್ವರಂ, ಬೆಂಗಳೂರು

Site Plan Map

Signature of the consultant

Note :- The Survey was carried out by this divining / Geophysical method of surveying is with our good knowledge and experience. However no guarantee of water will be given.